

## Brick Building

This building was Photocatalyst  $\text{TiO}_2$  treated in year 2000. The surfaces were pristine clean after 3+ years of exposure to pollution from autos and trucks on this high traffic city street.



The above picture is of the adjacent building on this busy street. Note the amount of dirt that is on the front surface of this building compared to the Photocatalyst  $\text{TiO}_2$  treated building. The owners of the treated building are very pleased with the results and performance of the  $\text{TiO}_2$  treatment. As you can see, it greatly enhances the appearance of their building.