



Abatement by Encasement:
Safeguarding People
while Saving Money®

Safe Encasement Systems
Phone (888) 277-8834 or
(702) 360-6111
www.safeencasement.com



Mold Remediation & Photocatalytic Coating Application at Carlton Hotel

The Challenge: The Carlton Hotel has been undergoing a complete renovation. During the renovation, the owner wanted to address an area of the lower level that has had mold and odor problems for quite some time.

The Solution: The Safe Encasement System for mold including the SE-110 and SE-130MR were used as a finish paint system to prevent the re-growth of mold. The SES Photocatalytic coating system with the PTA-85 and TPX-85 was used to provide a continuous PureZone of clean air for the entire space. The owner reported a dramatic odor improvement the old, bad smell is entirely gone.

