


TiO₂ Photocatalyst Treated Building



Toyohashi
Building, Japan

Photocatalyst TiO₂
Treatment was done
5-1/2 years ago

Only front half
(right side) of the
building was treated.



Close up of building wall
shows the
effectiveness of the
reduction in pollutants
that condense on the
walls and the mold
that's growing under
the window ledge on
the untreated walls.



Front wall is very close
to a high traffic
highway, and only the
left half of the wall
was treated.

Wipe test showing the
pollution & dirt that's
on the un-treated side
of the front wall.